CREW:	81 WORK ORDER TYPE: PD REPAIR	09-66504-0	ISSUE DATE 01/06/11	Page 1 Of 2				
Origi Plann	nator : DEAN WOOD Schedule Dater : ALAN DEWSNUP Priority	te : : 3A	Date Completed:	Failure Code:				
Drawing No : 2SGA-M2063B Clearance Equip No/Cat: 2SGA2 0 Tag Request Project ID : 2SGA-BLR-1 Text ID Shutdown : N No Shutdown Frequency		: NO :	Completed By :	Signature :	Signature :			
		: : NOT SCHEDULED	Accepted By :	Signature :				
				** Delay Codes Legend ** W=Whse C=CrSp T=Tag TL=Tool P=Plan ** Record Time Daily ** Delays				
Step	Job Scope		Additional Information	Emp No Date Hours	Code/Hrs			
7	Capital Project Work Order to install remove and replace all tube-to-header connections on two lower-waterwall heade frontwall, west side of Unit 2. FOR ADDITIONAL INFORMATION CONTACT: DEAN WOOD OR WILL LOVELL	1 1		** IMPORTANT NOTICE ** YOU ARE RESPONSIBLE FOR YOUR OWN SAFET ENSURE THAT THE REQUIRED PPE IS WORN F JOB YOU ARE DOING. IF YOU HAVE ANY QU CONCERNING THE WORK RULES, SAFETY CODE	OR EVERY ESTIONS			
		·		REQUIRED PPE, PLEASE CONTACT YOUR SUPE				
Job F	Feedback/Historical Notes:							

09-66504-0

		** Work Order Parts List **						
	Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	05250	WELD MATERIAL, ROD	S 511782	10/27/10	LB	10	0	10
2	05615	WELD MATERIAL, ROD	S 511782	10/27/10	LB	10	Ö	10
3	22469	TUBING, 02.50 OD	S 511434*	10/25/10	FT	227	0	227
4	23340	STEEL, PLATE	S 512276	10/29/10	SF	0	0	0
5	43209	WELD MATERIAL, MIG WIRE	S 514153	11/09/10	SP	1	0	1
6	53503	STEEL, PLATE	S 513144	11/03/10	SF	50	0	50
7	55729	WELD MATERIAL, CODE ELECTRODES	S 511782	10/27/10	LB	50	0	50
8	79766	STEEL, SQUARE BAR	S 512995*	11/03/10	FT	40	0	40
9	DIRECT	GAUGE, THICKNESS MEASURING, ULTRASONIC, 38DL PLUS, INCLUDES:	10-81905	06/30/10	EA	1	0	1
10	DIRECT	PROBE, THICKNESS, ULTRASONIC, OLYMPUS P/N D7908	10-81905	06/30/10	EA	1	0	1
11	DIRECT	SERVICE CONTRACT RELEASE FOR U-2 LOWER WATERWALL HEADER AND	11-45603-9	10/18/10	EA	1	0	0
12	DIRECT	BAR, COPPER, ROUND, 2.5" X 7.25"	11-85000	10/29/10	EA	1	0	1
13	DIRECT	PAYMENT FOR LOWER WATERWALL TUBE REPLACEMENT UNIT 2 2010 OUT	11-45603-9	11/03/10	EA	1	0	1
14	DIRECT	PAYMENT FOR THE LOWER WATER WALL HEADER AND TUBE WORK IN BOT	11-45603-9	11/05/10	EA	1	0	1
15	DIRECT	PAYMENT FOR WORK ON THE LOWER WATERWALL HEADER / TUBE WORK U	11-45603-9	11/12/10	EA	1	0	1
16	DIRECT	PAYMENT FOR LOWER WATER WALL HEADER WORK UNIT 2 2010 OUTAGE.	11-45603-9	11/19/10	EA	1	0	1
17	DIRECT	PAYMENT FOR REPAIRS ON THE LOWER WATER WALL HEADER, UNIT 2 2	11-45603-2	11/24/10	EA	1	0	1
18	DIRECT	PAYMENT FOR REPAIRS TO THE LOWER WATER WALL SECTION OF THE B	11-45603-4	12/02/10	EA	1	0	1